



1073893

Kootenai River


As clean fill material in this area sloughs-off the un-stabilized bank, vermiculite may become exposed below depths previously removed. As this occurs the repairs will be made to the cover material in these areas.

- Legend**  
**PLM-9002**
- ND for LA at < 1 foot
  - < 1% for LA at < 1 foot
  - ND for LA at 1-2 feet
  - < 1% LA at 1-2 feet
  - ND for LA at 2-3 feet
  - < 1% LA at 2-3 feet
  - ND for LA at 3-4 feet
  - < 1% LA at 3-4 feet
  - ND for LA at > 4 feet
  - < 1% LA at > 4 feet
  - Orange Snow Fence Barrier

**Residual Contamination**  
**Based on Investigation Activities**  
**and Confirmation Soil Sampling**

Kootenai River

- Legend**
- Visible Vermiculite**  
**PLM-VE Sampling Result**
- Low Levels of Visual Vermiculite
  - Medium Levels of Visual Vermiculite
  - High Levels of Visual Vermiculite
  - Not Sampled
  - Non-Detect
  - Trace
  - < 1
  - Operable Unit 1 Boundary
  - Area 1 - Former Export Plant
  - Area 2 - Riverside Park
- Note:** All results were obtained from laboratory EDDs and have not been through the Libby2 QA/QC process.



**Figure 4-1**  
**Operable Unit 1 2007**  
**Soil Investigation Results**  
**and**  
**Residual Contamination**  
Libby Asbestos Project  
Libby, Montana

